

Teckenförklaring

Geotekniska_Utlåtanden_region ID

[Diagonal hatching, top-left to bottom-right]	32
[Diagonal hatching, bottom-left to top-right]	38
[Cross-hatching]	85
[Pink fill]	98
[Blue diagonal hatching, top-left to bottom-right]	129
[Blue diagonal hatching, bottom-left to top-right]	146
[Yellow diagonal hatching, top-left to bottom-right]	163
[Cross-hatching]	173
[Yellow diagonal hatching, bottom-left to top-right]	175
[Yellow diagonal hatching, top-left to bottom-right]	177
[Orange diagonal hatching, top-left to bottom-right]	186
[Purple diagonal hatching, top-left to bottom-right]	197
[Blue diagonal hatching, top-left to bottom-right]	207
[Blue diagonal hatching, bottom-left to top-right]	214

0 50 100 200 300
Meter

1:8 000


Bilder från Brobäcken och Sätträbäcken




Brant stående slänt som hålls upp av tät vegetation.



Slänt i Brobäcken



0 10 20 30 40 50 100 m
SKALA 1:1000



BETECKNINGAR

Linjestil	Namn	Idtyp	Minvärde	Maxvärde	Medelvärde
	W1	W	8.206	8.816	8.464
	SMS120GW	RF	10.550	12.370	11.360
	W3	W	7.236	7.576	7.380
	SMS111GW	RF	6.240	8.070	7.507

FÖRKLARINGAR

- Torr
- Ersatt
- Funktionskontroll ok
- Hinder
- Fruset
- Flödar
- Avslutat
- Funktionskontroll ej ok
- Spolat